

Oil Field Environmental Incident Summary

Incident: 20131127102936 **Date/Time of Notice:** 11/27/2013 09:51

Responsible Party: CONDOR PETROLEUM, INC.

Well Operator: CONDOR PETROLEUM, INC.

Well Name: FEDERAL 2-1

Field Name: STONEVIEW

Well File #: 13348

Date Incident: 11/4/2013 **Time Incident:** 14:00

Facility ID Number:

County: DIVIDE

Twp: 160

Rng: 95

Sec: 2

Qtr: SE SW

Location Description:

Submitted By: JoAnn Klevenberg

Received By:

Contact Person: Dave Heilman
PO BOX 339
TIOGA, ND 58852

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Yes

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	0	barrels	0	barrels		
Other	40	barrels	0	barrels		

Description of Other Released Contaminant:

SW and oil

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

was contained inside dike, repair treater, pull sw out of dike

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 11/30/2013 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

This appears to be the location and incident that was reported to the ND DoH and NDIC by the US FWS. Release has been investigated by Scott Stockdill, off site impacts sampled, and samples transferred to the US FWS for laboratory analysis. From appearance of photos, this release, unless this is a new event, did not occur on Nov. 4, 2013. US FWS and US FS retains oversight and authority.